ECS Configuration Change Request Page 1 of **Pages** CCR No. 97-0477B **Logged Date** 6/16/97 Rev. Request Type **CCR Priority** Urgent X **Change Class** Routine Emergency **Affected Release** A II Title Update Pre-Release B NSIDC HW diagram baseline (Doc: 420-TD-051-003) Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or **Documents Affected Tech Reference RTM Change Start New Baseline Problem** Update NSIDC HW diagram for the following: 1. SPRHW-NSIDC-2D is attached to SPRHW-NSIDC-2 AITHW-NSIDC-2, CSS-NSIDC-1, MSS-NSIDC-1 and PLNHW-NSIDC-1 have each 4 GB internal drive PLNHW-NSIDC-1A is a 14X2 GB disk array **Proposed Solution** See attachment **Impact Analysis:** Organizations Affected: M&O ВОО ECS Chief Eng FOS Contracts QO 🗌 Procurement Rel. A X Rel. C SCDO Arch. Rel. Dev Science Off Security Subcontrct Sys. Eng Sys Verf Cost: None X Small Medium Large (Not exceeding \$100,000) (\$100,000 to \$500,000) (Over \$500,000) Schedule: Other None X Additional LOC Man-Months Materials Originator Evan Winston (Signed) Evan Winston 6/13/97 Date Office Pre B Testbed Office Manager (signed) N. Prasad 6/13/97 Signature for Rel A Manager Date **Disposition** Approved X Approved w/Comment Forward Disapproved Comments:

CM01OC96 ECS

6/13/97

Date

(signed) N. Prasad

Signature

CCB Chairperson